

# Riverstone Wastewater Treatment Plant 2018-19 Pollution Monitoring Summary



## EPL 1796

Summary period: 01-07-2018 to 30-06-2019

Date published: 09-09-2019

Licensee: Sydney Water Corporation

PO Box 399

PARRAMATTA NSW 2124

Table 1: 50 percentile yearly summary								
EPA Point 3 Site code RS0003		Point description: Downstream of the weir in the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	50 percentile limit	50 percentile value	within limits
carbonaceous biochemical oxygen demand	mg/L	every 6 days	61	<2	4	10	<2	yes
nitrogen (ammonia)	mg/L	every 6 days	61	0.01	5.96	1	0.03	yes
total suspended solids	mg/L	every 6 days	61	<2	36	10	<2	yes

Table 1: 50 percentile yearly summary								
EPA Point 4 Site code RS0004		Point description: At the outlet of the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	50 percentile limit	50 percentile value	within limits
Ceriodaphnia dubia immobilisation (EC50)	% Effluent/Vol	monthly	12	100	100	50	100	yes

# Riverstone Wastewater Treatment Plant 2018-19 Pollution Monitoring Summary

## EPL 1796

Summary period: 01-07-2018 to 30-06-2019

Date published: 09-09-2019



**Licensee:** Sydney Water Corporation  
PO Box 399  
PARRAMATTA NSW 2124

**Table 2: 80 percentile yearly summary**

EPA Point 4 Site code RS0004		Point description: At the outlet of the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	80 percentile limit	80 percentile value	within limits
faecal coliforms	CFU/100mL	every 6 days	61	<1	630	200	18	yes

# Riverstone Wastewater Treatment Plant 2018-19 Pollution Monitoring Summary

EPL 1796

Summary period: 01-07-2018 to 30-06-2019

Date published: 09-09-2019



Licensee: Sydney Water Corporation  
PO Box 399  
PARRAMATTA NSW 2124

**Table 3: 90 percentile yearly summary**

EPA Point 3 Site code RS0003		Point description: Downstream of the weir in the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	90 percentile limit	90 percentile value	within limit
aluminium	ug/L	monthly	12	35	720	3,200	700	yes
carbonaceous biochemical oxygen demand	mg/L	every 6 days	61	<2	4	15	<2	yes
cobalt	ug/L	monthly	12	0.3	2.3	8	1	yes
copper	ug/L	monthly	12	0.6	3	79	2.3	yes
cyanide	ug/L	monthly	12	<5	<5	240	<5	yes
iron	ug/L	monthly	12	10	288	650	47	yes
nickel	ug/L	monthly	12	1.4	4	120	3.7	yes
nitrogen (ammonia)	mg/L	every 6 days	61	0.01	5.96	5	0.28	yes
total suspended solids	mg/L	every 6 days	61	<2	36	15	3	yes
zinc	ug/L	monthly	12	7	38	990	17	yes

**Table 3: 90 percentile yearly summary**

EPA Point 4 Site code RS0004		Point description: At the outlet of the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	90 percentile limit	90 percentile value	within limit
chlorine (total residual)	mg/L	every 6 days	61	<0.04	0.14	0.1	<0.04	yes
hydrogen sulphide (unionised)	ug/L	monthly	12	<30	<30	340	<30	yes

# Riverstone Wastewater Treatment Plant 2018-19 Pollution Monitoring Summary

EPL 1796

Summary period: 01-07-2018 to 30-06-2019

Date published: 09-09-2019



**Licensee:** Sydney Water Corporation  
PO Box 399  
PARRAMATTA NSW 2124

**Table 4: 100 percentile yearly summary**

EPA Point 3 Site code RS0003		Point description: Downstream of the weir in the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	100 percentile limit	100 percentile value	within limits
nitrogen (total)	mg/L	every 6 days	61	0.68	27.3	45	27.3	yes
phosphorus	mg/L	every 6 days	61	0.02	0.5	5	0.5	yes

# Riverstone Wastewater Treatment Plant 2018-19 Pollution Monitoring Summary

EPL 1796

Summary period: 01-07-2018 to 30-06-2019

Date published: 09-09-2019



**Licensee:** Sydney Water Corporation  
PO Box 399  
PARRAMATTA NSW 2124

**Table 5: Average yearly summary**

EPA Point 3 Site code RS0003		Point description: Downstream of the weir in the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	Average limit	Average value	within limits
aluminium	ug/L	monthly	12	35	720	330	206	yes
cobalt	ug/L	monthly	12	0.3	2.3	2.9	0.7	yes
copper	ug/L	monthly	12	0.6	3	14.4	2	yes
cyanide	ug/L	monthly	12	<5	<5	21	<5	yes
iron	ug/L	monthly	12	10	288	380	44	yes
nickel	ug/L	monthly	12	1.4	4	35	3	yes
zinc	ug/L	monthly	12	7	38	70	12	yes

**Table 5: Average yearly summary**

EPA Point 4 Site code RS0004		Point description: At the outlet of the chlorine contact tank						
pollutant	unit of measure	sampling frequency	number of samples	minimum result	maximum result	Average limit	Average value	within limits
hydrogen sulphide (unionised)	ug/L	monthly	12	<30	<30	83	<30	yes